



RECEIVED NOV - 5 2018



BP America Production Company
L48 Onshore Operations
380 Airport Road
Durango, CO 81301

October 31, 2018

EPA Region 8
Office of Air
1595 Wynkoop St
Denver, CO 80202-1129

Colorado Department of Public Health and Environmental
Air Pollution Control Division
4300 Cherry Creek Dr South
Denver, CO 80246-1530

Subject: 40 CFR 60.5420a(b)
NSPS Subpart OOOOa Annual Report

RECEIVED

NOV 6 - 2018

Office of Enforcement, Compliance
and Environmental Justice

Dear Sir or Madam:

BP America Production Company (BP) is submitting this NSPS Subpart OOOOa Annual Report to fulfill the requirement of 40 CFR 60.5420a(b). Please find attached the necessary documentation for all NSPS OOOOa sources from 08/02/2017 to 08/02/2018.

If you have any questions regarding this notification, please do not hesitate to contact Erin Dunman, the field environmental advisor responsible for this report, by phone at (281) 810-2578 or by email at erin.dunman@bpx.com.

Based on information and belief formed after responsible inquiry, the statements and information in the attached document are true, accurate, and complete.

Sincerely,

DocuSigned by:

CFE4BE90485149C...

Will Burton
Vice President, Operation West BU

40 CFR Part 40 - Standards of Performance for Crude Oil and Natural Gas Facilities for which Construction, Modification or Reconstruction Commenced After September 18, 2015 - 40.5420a(h) Annual Report
For each affected facility, an owner or operator must include the information specified in paragraphs (b)(3)(i) through (iv) of this section in all annual reports.

The asterisk (*) next to each field indicates that the corresponding field is required.

Facility Record No. (Field value will automatically generate if a value is not entered.)	SITE INFORMATION		ALTERNATIVE ADDRESS INFORMATION (IF NO PHYSICAL ADDRESS AVAILABLE FOR SITE *)		REPORTING INFORMATION			
	Company Name * (40.5420a(h)(1)(i))	Facility Site Name * (40.5420a(h)(1)(ii))	US Well ID or US Well ID Associated with the Affected Facility, if applicable. * (40.5420a(h)(1)(iii))	Description of Site Location (40.5420a(h)(1)(iv))	Latitude of the Site (decimal degrees to 5 decimals using the North American Datum of 1983) (40.5420a(h)(1)(v))	Longitude of the Site (decimal degrees to 5 decimals using the North American Datum of 1983) (40.5420a(h)(1)(vi))	Beginning Date of Reporting Period * (40.5420a(h)(1)(vii))	Ending Date of Reporting Period * (40.5420a(h)(1)(viii))
e.g.: ABC Company	e.g.: XYZ Compressor Station	e.g.: 12 345-67890-12	e.g.: 7 miles NE of the intersection of Hwy 123 and Hwy 456	e.g.: 35.12345	e.g.: -101.12345	e.g.: 01/01/2016	e.g.: 06/30/2016	
1 BP America Production Company	ANDERSON C 1		05-067-07775-00	Well site in La Plata County, CO	37.17284	-107.66259	8/2/2015	8/2/2018
2 BP America Production Company	ANDERSON C 2		05-067-09886-00	Well site in La Plata County, CO	37.17343	-107.67169	8/2/2015	8/2/2018
3 BP America Production Company	ANDERSON C 3		05-067-09887-00	Well site in La Plata County, CO	37.17343	-107.67163	8/2/2015	8/2/2018
4 BP America Production Company	BARNES B 2		05-067-08773-00	Well site in La Plata County, CO	37.13736	-107.77136	8/2/2015	8/2/2018
5 BP America Production Company	BEUTEN A 4		05-067-09176-00	Well site in La Plata County, CO	37.07556	-107.63628	8/2/2015	8/2/2018
6 BP America Production Company	BROADFIELD CH 2		05-067-08653-00	Well site in La Plata County, CO	37.13754	-107.58805	8/2/2015	8/2/2018
7 BP America Production Company	BRVLE BROWN 2		05-067-07307-00	Well site in La Plata County, CO	37.09905	-107.80834	8/2/2015	8/2/2018
8 BP America Production Company	CUNIFF C 3		05-067-07176-00	Well site in La Plata County, CO	37.28405	-107.65587	8/2/2015	8/2/2018
9 BP America Production Company	CUNIFF FEDERAL A 2		05-067-08630-00	Well site in La Plata County, CO	37.28443	-107.66236	8/2/2015	8/2/2018
10 BP America Production Company	WARREN DAVIS C 2		05-067-09055-00	Well site in La Plata County, CO	37.10133	-107.78248	8/2/2015	8/2/2018
11 BP America Production Company	FC LEIDY OOL 3		05-067-08707-00	Well site in La Plata County, CO	37.13578	-107.81153	8/2/2015	8/2/2018
12 BP America Production Company	FC LEIDY COM 1		05-067-07409-00	Well site in La Plata County, CO	37.13564	-107.81633	8/2/2015	8/2/2018
13 BP America Production Company	FC SOUTHERN UTE COM 005 2		05-067-08776-00	Well site in La Plata County, CO	37.11891	-107.83771	8/2/2015	8/2/2018
14 BP America Production Company	FORD H 1		05-067-09956-00	Well site in La Plata County, CO	37.12127	-107.70731	8/2/2015	8/2/2018
15 BP America Production Company	FORD H 8		05-067-09956-00	Well site in La Plata County, CO	37.12118	-107.70732	8/2/2015	8/2/2018
16 BP America Production Company	FRANK FEDERAL 2		05-067-08862-00	Well site in La Plata County, CO	37.22292	-107.51282	8/2/2015	8/2/2018
17 BP America Production Company	CARIMILLA GALLAGHER A 1		05-067-06124-00	Well site in Archuleta County, CO	37.21869	-107.41190	8/2/2015	8/2/2018
18 BP America Production Company	HORTHER 31 03 3		05-067-09963-00	Well site in La Plata County, CO	37.07198	-107.54094	8/2/2015	8/2/2018
19 BP America Production Company	ARTHUR JONES A 8		05-067-09966-00	Well site in La Plata County, CO	37.07774	-107.58271	8/2/2015	8/2/2018
20 BP America Production Company	KLUSMAN RANCHES 1		05-067-06985-00	Well site in La Plata County, CO	37.11506	-107.68195	8/2/2015	8/2/2018
21 BP America Production Company	LARSEN 01 12 1		05-067-06767-00	Well site in La Plata County, CO	37.21921	-107.79990	8/2/2015	8/2/2018
22 BP America Production Company	MARTINEZ A 1		05-067-09823-00	Well site in La Plata County, CO	37.12895	-107.71889	8/2/2015	8/2/2018
23 BP America Production Company	MARTINEZ A 2		05-067-09826-00	Well site in La Plata County, CO	37.12841	-107.72605	8/2/2015	8/2/2018
24 BP America Production Company	MARTINEZ A 3		05-067-09823-00	Well site in La Plata County, CO	37.12895	-107.71300	8/2/2015	8/2/2018
25 BP America Production Company	MCCARVILLE A 2		05-067-09817-00	Well site in La Plata County, CO	37.10433	-107.80034	8/2/2015	8/2/2018
26 BP America Production Company	PETER PHILLIPS A 1		05-067-07028-00	Well site in La Plata County, CO	37.13611	-107.83291	8/2/2015	8/2/2018
27 BP America Production Company	PICCOLI A 1		05-067-07186-00	Well site in La Plata County, CO	37.14991	-107.79140	8/2/2015	8/2/2018
28 BP America Production Company	PICCOLI A 4		05-067-09307-00	Well site in La Plata County, CO	37.17561	-107.78836	8/2/2015	8/2/2018
29 BP America Production Company	REIDGES 1		05-067-09955-00	Well site in La Plata County, CO	37.28805	-107.54230	8/2/2015	8/2/2018
30 BP America Production Company	SALVADOR A 2		05-067-08778-00	Well site in La Plata County, CO	37.07951	-107.60955	8/2/2015	8/2/2018
31 BP America Production Company	SALVADOR A 4		05-067-08777-00	Well site in La Plata County, CO	37.07911	-107.60964	8/2/2015	8/2/2018
32 BP America Production Company	SNOOK B 1A 17		05-067-06295-00	Well site in La Plata County, CO	37.04335	-107.62839	8/2/2015	8/2/2018
33 BP America Production Company	SOUTHERN UTE 1 8 1		05-067-06003-00	Well site in La Plata County, CO	37.11327	-107.68839	8/2/2015	8/2/2018
34 BP America Production Company	SOUTHERN UTE 38 20 21 1 2		05-067-09562-00	Well site in La Plata County, CO	37.09630	-107.93337	8/2/2015	8/2/2018
35 BP America Production Company	SOUTHERN UTE ALLOTTE NC 2		05-067-08326-00	Well site in La Plata County, CO	37.18105	-107.75485	8/2/2015	8/2/2018
36 BP America Production Company	SOUTHERN UTE AX 2		05-067-09797-00	Well site in La Plata County, CO	37.13425	-107.64593	8/2/2015	8/2/2018
37 BP America Production Company	SOUTHERN UTE AX 4		05-067-09796-00	Well site in La Plata County, CO	37.13430	-107.64581	8/2/2015	8/2/2018
38 BP America Production Company	SOUTHERN UTE TRIBAL A 5 1		05-067-06796-00	Well site in La Plata County, CO	37.15126	-107.66906	8/2/2015	8/2/2018
39 BP America Production Company	SOUTHERN UTE TRIBAL BK 4		05-067-09951-00	Well site in La Plata County, CO	37.07103	-107.60745	8/2/2015	8/2/2018
40 BP America Production Company	SOUTHERN UTE TRIBAL D 2		05-067-09951-00	Well site in La Plata County, CO	37.18024	-107.57884	8/2/2015	8/2/2018
41 BP America Production Company	SOUTHERN UTE TRIBAL L 1		05-067-09950-00	Well site in La Plata County, CO	37.07972	-107.60131	8/2/2015	8/2/2018
42 BP America Production Company	SOUTHERN UTE TRIBAL L 4		05-067-09952-00	Well site in La Plata County, CO	37.07310	-107.60742	8/2/2015	8/2/2018
43 BP America Production Company	SOUTHERN UTE TRIBAL O 1		05-067-07023-00	Well site in La Plata County, CO	37.12895	-107.63694	8/2/2015	8/2/2018
44 BP America Production Company	SOUTHERN UTE VS TRIBAL		05-067-07080-00	Well site in La Plata County, CO	37.11586	-107.62813	8/2/2015	8/2/2018
45 BP America Production Company	UTE AA 1		05-067-06746-00	Well site in La Plata County, CO	37.09414	-107.63651	8/2/2015	8/2/2018
46 BP America Production Company	WEBB REEDER B 2		05-067-08885-00	Well site in La Plata County, CO	37.22732	-107.82437	8/2/2015	8/2/2018
47 BP America Production Company	WRIGHT 05 13 1		05-067-06356-00	Well site in La Plata County, CO	37.17956	-107.54277	8/2/2015	8/2/2018
48 BP America Production Company	SOUTHERN UTE TRIBAL BK 2		05-067-09964-00	Well site in La Plata County, CO	37.07065	-107.62689	8/2/2015	8/2/2018
49 BP America Production Company	SOUTHERN UTE TRIBAL K 4		05-067-09964-00	Well site in La Plata County, CO	37.15591	-107.63663	8/2/2015	8/2/2018
50 BP America Production Company	SOUTHERN UTE TRIBAL O 3		05-067-09952-00	Well site in La Plata County, CO	37.12887	-107.62699	8/2/2015	8/2/2018
51 BP America Production Company	SOUTHERN UTE TRIBAL L 3		05-067-09959-00	Well site in La Plata County, CO	37.08519	-107.60946	8/2/2015	8/2/2018
52 BP America Production Company	CARMI LITA GALLAGHER A 3		05-067-06325-00	Well site in Archuleta County, CO	37.03309	-107.41121	8/2/2015	8/2/2018
53 BP America Production Company	LEIGH BARNES A 2		05-067-08207-00	Well site in La Plata County, CO	37.12608	-107.60732	8/2/2015	8/2/2018
54 BP America Production Company	SOUTHERN UTE 38 1 1		05-067-06528-00	Well site in La Plata County, CO	37.15023	-107.61697	8/2/2015	8/2/2018
55 BP America Production Company	SALVADOR US CENTRAL DELIVERY POINT		Not applicable	Compressor station in La Plata County, CO	37.07905	-107.61829	8/2/2015	8/2/2018
56 BP America Production Company	KLUSMAN A 1		05-067-07862-00	Well site in La Plata County, CO	37.13703	-107.70821	8/2/2015	8/2/2018
57 BP America Production Company	PETER PHILLIPS A 2		05-067-08739-00	Well site in La Plata County, CO	37.13588	-107.83440	8/2/2015	8/2/2018
58 BP America Production Company	PHILLIPS A 1		05-067-08882-00	Well site in La Plata County, CO	37.14531	-107.82593	8/2/2015	8/2/2018
59 BP America Production Company	SOUTHERN UTE AD 1		05-067-07582-00	Well site in La Plata County, CO	37.17991	-107.50783	8/2/2015	8/2/2018
60 BP America Production Company	SOUTHERN UTE M 2		05-067-09758-00	Well site in La Plata County, CO	37.10306	-107.67204	8/2/2015	8/2/2018
61 BP America Production Company	BAYFIELD FEDERAL 1		05-067-07154-00	Well site in La Plata County, CO	37.21766	-107.46521	8/2/2015	8/2/2018
62 BP America Production Company	ARTHUR JONES A 1		05-067-07024-00	Well site in La Plata County, CO	37.07747	-107.54319	8/2/2015	8/2/2018
63 BP America Production Company	BEUTEN A 1 1		05-067-06831-00	Well site in La Plata County, CO	37.07076	-107.62696	8/2/2015	8/2/2018
64 BP America Production Company	BROADFIELD CH 1		05-067-07836-00	Well site in La Plata County, CO	37.13714	-107.60676	8/2/2015	8/2/2018
65 BP America Production Company	BROADFIELD CH 3		05-067-09554-00	Well site in La Plata County, CO	37.13739	-107.60609	8/2/2015	8/2/2018
66 BP America Production Company	EAST SAULS CREEK 26 1 1		05-067-10001-00	Well site in La Plata County, CO	37.27498	-107.51156	8/2/2015	8/2/2018
67 BP America Production Company	EAST SAULS CREEK 26 1 2		05-067-10000-00	Well site in La Plata County, CO	37.27499	-107.51162	8/2/2015	8/2/2018
68 BP America Production Company	FISCHER MARK FEDERAL B 5		05-067-10003-00	Well site in La Plata County, CO	37.21872	-107.52702	8/2/2015	8/2/2018
69 BP America Production Company	FISCHER MARK FEDERAL B 1		05-067-07073-00	Well site in La Plata County, CO	37.21871	-107.52752	8/2/2015	8/2/2018
70 BP America Production Company	GEARHART 01 32 01		05-067-06546-00	Well site in La Plata County, CO	37.25413	-107.66492	8/2/2015	8/2/2018
71 BP America Production Company	GLOVER 4		05-067-06329-00	Well site in Archuleta County, CO	37.03889	-107.46222	8/2/2015	8/2/2018
72 BP America Production Company	KERRIGAN 32 6 2 1		05-067-06148-00	Well site in Archuleta County, CO	37.04245	-107.47371	8/2/2015	8/2/2018
73 BP America Production Company	KERRIGAN 32 6 2 3		05-067-06329-00	Well site in Archuleta County, CO	37.04245	-107.47371	8/2/2015	8/2/2018
74 BP America Production Company	KLUSMAN A 3		05-067-09708-00	Well site in La Plata County, CO	37.13713	-107.70861	8/2/2015	8/2/2018
75 BP America Production Company	LARSEN 01 12 3		05-067-08739-00	Well site in La Plata County, CO	37.21957	-107.80530	8/2/2015	8/2/2018
76 BP America Production Company	LE PLATT B 2		05-067-10024-00	Well site in La Plata County, CO	37.22130	-107.60395	8/2/2015	8/2/2018
77 BP America Production Company	LUCHINI 32 6 1 2		05-067-08328-00	Well site in Archuleta County, CO	37.08320	-107.49989	8/2/2015	8/2/2018
78 BP America Production Company	MARQUEZ A 2		05-067-06327-00	Well site in Archuleta County, CO	37.08307	-107.49979	8/2/2015	8/2/2018
79 BP America Production Company	PHILLIPS A 3 B 2		05-067-09881-00	Well site in La Plata County, CO	37.14553	-107.82666	8/2/2015	8/2/2018
80 BP America Production Company	PICCOLI A 2		05-067-08968-00	Well site in La Plata County, CO	37.17536	-107.78854	8/2/2015	8/2/2018
81 BP America Production Company	PICCOLI A 3		05-067-09360-00	Well site in La Plata County, CO	37.17563	-107.78873	8/2/2015	8/2/2018
82 BP America Production Company	SALVADOR A 1		05-067-06799-00	Well site in La Plata County, CO	37.07951	-107.62922	8/2/2015	8/2/2018
83 BP America Production Company	SEMLER A 2		05-067-08883-00	Well site in La Plata County, CO	37.13860	-107.67181	8/2/2015	8/2/2018
84 BP America Production Company	SEMLER A 4		05-067-08893-00	Well site in La Plata County, CO	37.13842	-107.67058	8/2/2015	8/2/2018
85 BP America Production Company	SOUTHERN UTE 32 08 03 07		05-067-08284-00	Well site in La Plata County, CO	37.09508	-107.60960	8/2/2015	8/2/2018
86 BP America Production Company	SOUTHERN UTE BK 2		05-067-08891-00	Well site in La Plata County, CO	37.10837	-107.68097	8/2/2015	8/2/2018
87 BP America Production Company	SOUTHERN UTE M 1		05-067-07025-00	Well site in La Plata County, CO	37.10200	-107.66250	8/2/2015	8/2/2018
88 BP America Production Company	SOUTHERN UTE BK 1		05-067-08630-00	Well site in La Plata County, CO	37.07123	-107.60809	8/2/2015	8/2/2018
89 BP America Production Company	SOUTHERN UTE TRIBAL E 1		05-067-06758-00	Well site in La Plata County, CO	37.08623	-107.60991	8/2/2015	8/2/2018
90 BP America Production Company	SOUTHERN UTE TRIBAL E 2		05-067-09993-00	Well site in La Plata County, CO	37.10002	-107.61138	8/2/2015	8/2/2018
91 BP America Production Company	SOUTHERN UTE TRIBAL K 1		05-067-07079-01	Well site in La Plata County, CO	37.13402	-107.63720	8/2/2015	8/2/2018
92 BP America Production Company	STATE MZ 1 R		05-067-08858-00	Well site in La Plata County, CO	37.20789	-107.54591	8/2/2015	8/2/2018
93 BP America Production Company	STATE MZ 2		05-067-10000-00	Well site in La Plata County, CO	37.20908	-107.54947	8/2/2015	8/2/2018
94 BP America Production Company	TIFFANY 1 1		05-067-09573-00	Well site in La Plata County, CO	37.10102	-107.55621	8/2/2015	8/2/2018
95 BP America Production Company	TIFFANY 1 2		05-067-09578-00	Well site in La Plata County, CO	37.10108	-107.55557	8/2/2015	8/2/2018
96 BP America Production Company	TIFFANY 1 3		05-067-09581-00	Well site in La Plata County, CO	37.10177	-107.55557	8/2/2015	8/2/2018
97 BP America Production Company	TIFFANY 1 4		05-067-09582-00	Well site in La Plata County, CO	37.10166	-107.55557	8/2/2015	8/2/2

For the collection of fugitive emissions components at each well site and the collection of fugitive emissions components at each compressor station within the company-defined area, an owner or operator must include the records of each monitoring survey including the information specified

The asterisk (*) next to each field indicates that the corresponding field is required.

Facility Record No. * (Select from dropdown list - may need to scroll up)	Identification of Each Affected Facility * (\$60.5420a(b)(1))	Date of Survey * (\$60.5420a(b)(7)(i))	Survey Begin Time * (\$60.5420a(b)(7)(ii))	Survey End Time * (\$60.5420a(b)(7)(iii))	Name of Surveyor * (\$60.5420a(b)(7)(iv))	Ambient Temperature During Survey * (\$60.5420a(b)(7)(v))	Sky Conditions During Survey * (\$60.5420a(b)(7)(vi))	Maximum Wind Speed During Survey * (\$60.5420a(b)(7)(vii))	Monitoring Instrument Used * (\$60.5420a(b)(7)(viii))	Deviations From Monitoring Plan (If none, state none.) * (\$60.5420a(b)(7)(ix))	Type of Component for which Fugitive Emissions Detected * (\$60.5420a(b)(7)(x))	Number of Each Component Type for which Fugitive Emissions Detected * (\$60.5420a(b)(7)(xi))	Type of Component Not Repaired as Required in § 60.5397a(h) * (\$60.5420a(b)(7)(xii))	Number of Each Component Type Not Repaired as Required in § 60.5397a(h) * (\$60.5420a(b)(7)(xiii))
	e.g.: Well Site ABC	e.g.: 8/13/17	e.g.: 10:00 am	e.g.: 1:00 pm	e.g.: John Smith	e.g.: 90°F	e.g.: Sunny, no clouds	e.g.: 2 mph	e.g.: Company ABC optical gas imaging camera	e.g.: None	e.g.: Valve	e.g.: 3	e.g.: Valve	e.g.: 1
1	ANDERSON C 1	10/26/2017	12:46 PM	1:49 PM	Erin Dunman	55	Clear	0.6	FLIR G320 optical gas imaging camera	None	Valve	1		
1	ANDERSON C 1	5/1/2018	12:20 PM	12:41 PM	Erin Dunman	58	Cloudy	6.5	FLIR G320 optical gas imaging camera	None	No fugitive emissions detected			
2	ANDERSON C 2	10/26/2017	1:08 PM	1:38 PM	Erin Dunman	61	Clear	1.2	FLIR G320 optical gas imaging camera	None	Valve	1		
2	ANDERSON C 2	5/1/2018	12:43 PM	1:17 PM	Erin Dunman	59	Cloudy	6.5	FLIR G320 optical gas imaging camera	None	No fugitive emissions detected			
3	ANDERSON C 3	10/26/2017	2:08 PM	2:38 PM	Erin Dunman	61	Clear	1.2	FLIR G320 optical gas imaging camera	None	No fugitive emissions detected			
3	ANDERSON C 3	5/1/2018	12:43 PM	1:17 PM	Erin Dunman	59	Cloudy	6.7	FLIR G320 optical gas imaging camera	None	Connector	1		
62	ARTHUR JONES A 1	4/25/2018	3:20 PM	3:44 PM	Erin Dunman	75	Clear	4.6	FLIR G320 optical gas imaging camera	None	Instrument	1		
19	ARTHUR JONES A 3	11/8/2017	1:37 PM	2:03 PM	Erin Dunman	49	Clear	3.7	FLIR G320 optical gas imaging camera	None	No fugitive emissions detected			
19	ARTHUR JONES A 3	4/25/2018	3:20 PM	3:44 PM	Erin Dunman	75	Clear	4.6	FLIR G320 optical gas imaging camera	None	No fugitive emissions detected			
7	ARVIL BROWN 2	11/14/2017	2:10 PM	2:56 PM	Erin Dunman	62	Clear	2.2	FLIR G320 optical gas imaging camera	None	Valve, Instrument	1 Valve & 1 Instrument		
7	ARVIL BROWN 2	6/3/2018	12:27 PM	1:17 PM	Erin Dunman	86	Clear	3.9	FLIR G320 optical gas imaging camera	None	Connector	1		
4	BARNES B 2	11/16/2017	3:35 PM	4:00 PM	Erin Dunman	60	Cloudy	5	FLIR G320 optical gas imaging camera	None	No fugitive emissions detected			

Facility Record No. * (Select from dropdown list - may need to scroll up)	Identification of Each Affected Facility * (\$60.5420a(b)(1))	Date of Survey * (\$60.5420a(b)(7)(i))	Survey Begin Time * (\$60.5420a(b)(7)(iii))	Survey End Time * (\$60.5420a(b)(7)(iii))	Name of Surveyor * (\$60.5420a(b)(7)(iii))	Ambient Temperature During Survey * (\$60.5420a(b)(7)(v))	Sky Conditions During Survey * (\$60.5420a(b)(7)(iv))	Maximum Wind Speed During Survey * (\$60.5420a(b)(7)(iv))	Monitoring Instrument Used * (\$60.5420a(b)(7)(vi))	Deviations From Monitoring Plan (If none, state none.) * (\$60.5420a(b)(7)(vi))	Type of Component for which Fugitive Emissions Detected * (\$60.5420a(b)(7)(viii))	Number of Each Component Type for which Fugitive Emissions Detected * (\$60.5420a(b)(7)(viii))	Type of Component Not Repaired as Required in § 60.5397a(h) * (\$60.5420a(b)(7)(viii))	Number of Each Component Type Not Repaired as Required in § 60.5397a(h) * (\$60.5420a(b)(7)(viii))
4	BARNES B 2	6/11/2018	2:40 PM	3:13 PM	Erin Dunman	84	Clear	5.8	FLIR G320 optical gas imaging camera	None	No fugitive emissions detected			
61	BAYFIELD FEDERAL 1	10/10/2017	2:35 PM	3:10 PM	Erin Dunman	53	Clear	2.6	FLIR G320 optical gas imaging camera	None	Instrument	1		
61	BAYFIELD FEDERAL 1	4/26/2018	12:20 PM	12:41 PM	Erin Dunman	69	Clear	5.1	FLIR G320 optical gas imaging camera	None	No fugitive emissions detected			
63	BEUTEN A 1 S	6/19/2018	11:15 AM	11:50 AM	Erin Dunman	79	Clear	6.1	FLIR G320 optical gas imaging camera	None	No fugitive emissions detected			
5	BEUTEN A 4	11/3/2017	12:23 PM	12:52 AM	Erin Dunman	54	Clear	3.3	FLIR G320 optical gas imaging camera	None	No fugitive emissions detected			
5	BEUTEN A 4	5/18/2018	11:13 AM	11:37 AM	Erin Dunman	68	Clear	4.6	FLIR G320 optical gas imaging camera	None	No fugitive emissions detected			
64	BRADFIELD CH 1	10/11/2017	2:12 PM	2:40 PM	Erin Dunman	65	Clear	2.3	FLIR G320 optical gas imaging camera	None	No fugitive emissions detected			
64	BRADFIELD CH 1	3/28/2018	10:50 AM	11:15 AM	Erin Dunman	39	Partly Cloudy	3.2	FLIR G320 optical gas imaging camera	None	No fugitive emissions detected			
6	BRADFIELD CH 2	10/11/2017	2:50 PM	3:40 PM	Erin Dunman	65	Clear	1.7	FLIR G320 optical gas imaging camera	None	Connector, Valve	2 Connector & 1 Valve		
6	BRADFIELD CH 2	3/28/2018	10:10 AM	10:45 AM	Erin Dunman	38	Partly Cloudy	3.6	FLIR G320 optical gas imaging camera	None	Connector	1		
65	BRADFIELD CH 3	3/28/2018	10:50 AM	11:15 AM	Erin Dunman	39	Partly Cloudy	3.2	FLIR G320 optical gas imaging camera	None	No fugitive emissions detected			
17	CARMELITA GALLEGOS A 1	11/8/2017	3:13 PM	4:00 PM	Erin Dunman	51	Clear	3.1	FLIR G320 optical gas imaging camera	None	Instrument	1		
17	CARMELITA GALLEGOS A 1	5/18/2018	1:41 PM	2:16 PM	Erin Dunman	77	Clear	5.3	FLIR G320 optical gas imaging camera	None	No fugitive emissions detected			
52	CARMELITA GALLEGOS A 3	11/8/2017	3:00 PM	3:46 PM	Erin Dunman	52	Clear	3.1	FLIR G320 optical gas imaging camera	None	Connector	1		

Facility Record No. * (Select from dropdown list - may need to scroll up)	Identification of Each Affected Facility * (\$60.5420a(b)(1))	Date of Survey * (\$60.5420a(b)(7)(i))	Survey Begin Time * (\$60.5420a(b)(7)(ii))	Survey End Time * (\$60.5420a(b)(7)(iii))	Name of Surveyor * (\$60.5420a(b)(7)(iv))	Ambient Temperature During Survey * (\$60.5420a(b)(7)(v))	Sky Conditions During Survey * (\$60.5420a(b)(7)(vi))	Maximum Wind Speed During Survey * (\$60.5420a(b)(7)(vii))	Monitoring Instrument Used * (\$60.5420a(b)(7)(viii))	Deviations From Monitoring Plan (if none, state none.) * (\$60.5420a(b)(7)(ix))	Type of Component for which Fugitive Emissions Detected * (\$60.5420a(b)(7)(x))	Number of Each Component Type for which Fugitive Emissions Detected * (\$60.5420a(b)(7)(xi))	Type of Component Not Repaired as Required in § 60.5397a(h) * (\$60.5420a(b)(7)(xii))	Number of Each Component Type Not Repaired as Required in § 60.5397a(h) * (\$60.5420a(b)(7)(xiii))
52	CARMELITA GALLEGOS A 3	5/18/2018	1:41 PM	2:16 PM	Erin Dunman	77	Clear	5.3	FLIR G320 optical gas imaging camera	None	Instrument	1		
8	CUNDIFF C 1	11/28/2017	2:16 PM	3:14 PM	Erin Dunman	50	Clear	1.7	FLIR G320 optical gas imaging camera	None	No fugitive emissions detected			
8	CUNDIFF C 1	6/4/2018	1:18 PM	2:00 PM	Erin Dunman	83	Clear	4.5	FLIR G320 optical gas imaging camera	None	No fugitive emissions detected			
9	CUNDIFF FEDERAL A 2	11/28/2017	1:47 PM	2:14 PM	Erin Dunman	49	Clear	1.1	FLIR G320 optical gas imaging camera	None	Open-ended Lines	1		
9	CUNDIFF FEDERAL A 2	6/4/2018	1:18 PM	2:00 PM	Erin Dunman	83	Clear	4.5	FLIR G320 optical gas imaging camera	None	No fugitive emissions detected			
66	EAST SAULS CREEK 26 1 1	12/13/2017	12:01 PM	12:28 PM	Erin Dunman	43	Partly Cloudy	1.3	FLIR G320 optical gas imaging camera	None	No fugitive emissions detected			
66	EAST SAULS CREEK 26 1 1	5/29/2018	1:55 PM	2:30 PM	Erin Dunman	74	Clear	2.7	FLIR G320 optical gas imaging camera	None	No fugitive emissions detected			
67	EAST SAULS CREEK 26 1 2	12/13/2017	12:01 PM	12:28 PM	Erin Dunman	43	Partly Cloudy	1.3	FLIR G320 optical gas imaging camera	None	No fugitive emissions detected			
67	EAST SAULS CREEK 26 1 2	5/29/2018	1:55 PM	2:30 PM	Erin Dunman	74	Clear	2.4	FLIR G320 optical gas imaging camera	None	No fugitive emissions detected			
12	FC LEIDY COM 1	6/11/2018	12:20 PM	1:00 PM	Erin Dunman	84	Clear	4.3	FLIR G320 optical gas imaging camera	None	No fugitive emissions detected			
11	FC LEIDY 001 2	11/16/2017	3:10 PM	4:00 PM	Erin Dunman	57	Cloudy	3.3	FLIR G320 optical gas imaging camera	None	No fugitive emissions detected			
11	FC Leidy 001 2	6/11/2018	12:20 PM	1:00 PM	Erin Dunman	84	Clear	4.3	FLIR G320 optical gas imaging camera	None	No fugitive emissions detected			
12	FC LEIDY COM 1	11/29/2017	2:35 PM	3:02 PM	Erin Dunman	54	Cloudy	2.2	FLIR G320 optical gas imaging camera	None	Connector	2		
13	FC SOUTHERN UTE COM 005 2	6/21/2018	2:48 PM	3:30 PM	Erin Dunman	91	Clear	7.2	FLIR G320 optical gas imaging camera	None	Valve	1		

Facility Record No. * (Select from dropdown list - may need to scroll up)	Identification of Each Affected Facility * (\$60.5420a(b)(1))	Date of Survey * (\$60.5420a(b)(7)(i))	Survey Begin Time * (\$60.5420a(b)(7)(ii))	Survey End Time * (\$60.5420a(b)(7)(iii))	Name of Surveyor * (\$60.5420a(b)(7)(iv))	Ambient Temperature During Survey * (\$60.5420a(b)(7)(v))	Sky Conditions During Survey * (\$60.5420a(b)(7)(vi))	Maximum Wind Speed During Survey * (\$60.5420a(b)(7)(vii))	Monitoring Instrument Used * (\$60.5420a(b)(7)(viii))	Deviations From Monitoring Plan (if none, state none.) * (\$60.5420a(b)(7)(ix))	Type of Component for which Fugitive Emissions Detected * (\$60.5420a(b)(7)(x))	Number of Each Component Type for which Fugitive Emissions Detected * (\$60.5420a(b)(7)(xi))	Type of Component Not Repaired as Required in § 60.5397a(h) * (\$60.5420a(b)(7)(xii))	Number of Each Component Type Not Repaired as Required in § 60.5397a(h) * (\$60.5420a(b)(7)(xiii))
13	FC SOUTHERN UTE COM 005 2	11/14/2017	12:16 PM	12:45 AM	Erin Dunman	62	Clear	3.5	FLIR G320 optical gas imaging camera	None	Connector	1		
69	Fischer Mark Federal B 1	5/29/2018	1:07 PM	1:33 PM	Erin Dunman	70	Clear	1.8	FLIR G320 optical gas imaging camera	None	No fugitive emissions detected			
68	FISCHER MARK FEDERAL B 5	11/22/2018	12:01 PM	12:30 PM	Erin Dunman	52	Clear	3.4	FLIR G320 optical gas imaging camera	None	No fugitive emissions detected			
68	FISCHER MARK FEDERAL B 5	5/29/2018	1:07 PM	1:33 PM	Erin Dunman	70	Clear	1.8	FLIR G320 optical gas imaging camera	None	No fugitive emissions detected			
14	FORD H 1	10/18/2017	10:10 AM	11:18 AM	Erin Dunman	51	Partly Cloudy	1.9	FLIR G320 optical gas imaging camera	None	Connector	2		
14	FORD H 1	3/1/2018	1:44 PM	2:46 PM	Erin Dunman	50	Clear	2.8	FLIR G320 optical gas imaging camera	None	No fugitive emissions detected			
15	FORD H 3	10/18/2017	10:10 AM	11:18 AM	Erin Dunman	51	Partly Cloudy	1.9	FLIR G320 optical gas imaging camera	None	Connector	1		
15	FORD H 3	3/1/2018	1:44 PM	2:46 PM	Erin Dunman	50	Clear	2.8	FLIR G320 optical gas imaging camera	None	No fugitive emissions detected			
16	FRAHM FEDERAL 2	11/28/2018	12:53 PM	1:16 PM	Erin Dunman	48	Clear	2.7	FLIR G320 optical gas imaging camera	None	No fugitive emissions detected			
16	FRAHM FEDERAL 2	5/29/2018	12:17 PM	12:41 PM	Erin Dunman	69	Clear	1.8	FLIR G320 optical gas imaging camera	None	No fugitive emissions detected			
70	GEARHART 01 32 01	6/11/2018	3:29 PM	4:03 PM	Erin Dunman	88	Clear	3.4	FLIR G320 optical gas imaging camera	None	Open-ended Lines, Connector, Pneumatic Controller	1 Open-ended Lines, 2 Connector & 1 Pneumatic		
71	GLOVER 4	7/19/2018	12:30 PM	1:15 PM	Erin Dunman	89	Partly Cloudy	4	FLIR G320 optical gas imaging camera	None	No fugitive emissions detected			
18	HORTHER 31 03 3	11/13/2017	2:30 PM	3:01 PM	Erin Dunman	64	Clear	3.3	FLIR G320 optical gas imaging camera	None	No fugitive emissions detected			
18	HORTHER 31 03 3	5/18/2018	3:14 PM	3:40 PM	Erin Dunman	76	Clear	5.2	FLIR G320 optical gas imaging camera	None	Connector	1		

Facility Record No. * (Select from dropdown list - may need to scroll up)	Identification of Each Affected Facility * (\$60.5420a(b)(1))	Date of Survey * (\$60.5420a(b)(7)(i))	Survey Begin Time * (\$60.5420a(b)(7)(iii))	Survey End Time * (\$60.5420a(b)(7)(iii))	Name of Surveyor * (\$60.5420a(b)(7)(iii))	Ambient Temperature During Survey * (\$60.5420a(b)(7)(v))	Sky Conditions During Survey * (\$60.5420a(b)(7)(iv))	Maximum Wind Speed During Survey * (\$60.5420a(b)(7)(iv))	Monitoring Instrument Used * (\$60.5420a(b)(7)(v))	Deviations From Monitoring Plan (If none, state none.) * (\$60.5420a(b)(7)(vi))	Type of Component for which Fugitive Emissions Detected * (\$60.5420a(b)(7)(vii))	Number of Each Component Type for which Fugitive Emissions Detected * (\$60.5420a(b)(7)(vii))	Type of Component Not Repaired as Required In (\$60.5397a(h) * (\$60.5420a(b)(7)(viii))	Number of Each Component Type Not Repaired as Required In § 60.5397a(h) * (\$60.5420a(b)(7)(viii))
72	KERRIGAN 32 6 2 1	5/18/2018	2:34 PM	3:00 PM	Erin Dunman	78	Clear	5	FLIR G320 optical gas imaging camera	None	No fugitive emissions detected			
73	KERRIGAN 32 6 2 3	5/18/2018	2:34 PM	2:57 PM	Erin Dunman	78	Clear	5	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
56	KLUSMAN A 1	8/25/2017	1:00 PM	1:45 PM	Erin Dunman	79	Clear	12.1	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
56	KLUSMAN A 1	3/8/2018	2:49 PM	3:17 PM	Erin Dunman	53	Clear	4.5	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
74	KLUSMAN A 3	3/7/2018	2:49 PM	3:17 PM	Erin Dunman	53	Clear	4.5	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
20	KLUSMAN RANCHES 1	11/6/2017	3:47 PM	3:20 PM	Erin Dunman	56	Cloudy	6.4	FLIR G320 optical gas imaging camera		Connector	1		
20	KLUSMAN RANCHES 1	5/10/2018	1:19 PM	2:02 PM	Erin Dunman	81	Clear	1.8	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
21	LARSEN 01 12 1	11/15/2017	10:14 AM	11:00 AM	Erin Dunman	59	Partly Cloudy	1.8	FLIR G320 optical gas imaging camera		Connector	1		
21	LARSEN 01 12 1	4/26/2018	1:07 PM	1:34 PM	Erin Dunman	71	Clear	6.4	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
75	LARSEN 01 12 2	4/26/2018	1:36 PM	2:25 AM	Erin Dunman	76	Clear	7.7	FLIR G320 optical gas imaging camera		Instrument	3		
76	LE PLATT B 2	4/26/2018	11:23 AM	12:00 PM	Erin Dunman	65	Clear	2.5	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
53	LEIDY BARNES A 2	11/14/2017	1:20 PM	1:50 PM	Erin Dunman	62	Clear	3.1	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
53	LEIDY BARNES A 2	6/5/2018	11:50 AM	12:15 PM	Erin Dunman	84	Clear	2.3	FLIR G320 optical gas imaging camera		Valve	1		
77	LUCHINI 32 6 12 2	5/18/2018	12:42 PM	1:20 PM	Erin Dunman	71	Clear	5.1	FLIR G320 optical gas imaging camera		No fugitive emissions detected			

Facility Record No. * (Select from dropdown list - may need to scroll up)	Identification of Each Affected Facility * (\$60.5420a(b)(1))	Date of Survey * (\$60.5420a(b)(7)(i))	Survey Begin Time * (\$60.5420a(b)(7)(ii))	Survey End Time * (\$60.5420a(b)(7)(iii))	Name of Surveyor * (\$60.5420a(b)(7)(iv))	Ambient Temperature During Survey * (\$60.5420a(b)(7)(v))	Sky Conditions During Survey * (\$60.5420a(b)(7)(vi))	Maximum Wind Speed During Survey * (\$60.5420a(b)(7)(vii))	Monitoring Instrument Used * (\$60.5420a(b)(7)(viii))	Deviations From Monitoring Plan (If none, state none.) * (\$60.5420a(b)(7)(ix))	Type of Component for which Fugitive Emissions Detected * (\$60.5420a(b)(7)(x))	Number of Each Component Type for which Fugitive Emissions Detected * (\$60.5420a(b)(7)(xi))	Type of Component Not Repaired as Required in § 60.5397a(h) * (\$60.5420a(b)(7)(xii))	Number of Each Component Type Not Repaired as Required in § 60.5397a(h) * (\$60.5420a(b)(7)(xiii))
78	MARQUEZ A 2	5/18/2018	12:42 PM	1:20 PM	Erin Dunman	71	Clear	5.1	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
22	MARTINEZ A 1	10/18/2017	11:33 AM	12:24 AM	Erin Dunman	58	Partly Cloudy	2.8	FLIR G320 optical gas imaging camera		Connector, Instrument	1 Connector & 1 Instrument		
22	MARTINEZ A 1	3/7/2018	2:05 PM	2:39 PM	Erin Dunman	53	Clear	2.3	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
23	MARTINEZ A 2	10/18/2017	12:35 PM	1:00 PM	Erin Dunman	62	Partly Cloudy	1.7	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
23	MARTINEZ A 2	3/1/2018	2:38 PM	3:00 PM	Erin Dunman	48	Clear	3.6	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
24	MARTINEZ A 3	10/18/2017	11:33 AM	12:24 AM	Erin Dunman	58	Partly Cloudy	2.8	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
24	MARTINEZ A 3	3/7/2018	2:05 PM	2:39 PM	Erin Dunman	53	Clear	2.3	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
25	MCCARVILLE A 2	11/14/2017	2:52 PM	3:20 PM	Erin Dunman	63	Clear	4.4	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
25	MCCARVILLE A 2	6/5/2018	12:55 PM	1:15 PM	Erin Dunman	90	Clear	4.2	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
26	PETER PHILLIPS A 1	11/29/2018	12:00 PM	2:43 PM	Erin Dunman	54	Cloudy	0.7	FLIR G320 optical gas imaging camera		Instrument	1		
26	PETER PHILLIPS A 1	6/11/2018	11:30 AM	12:20 PM	Erin Dunman	81	Clear	2.1	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
57	PETER PHILLIPS A 2	8/25/2017	2:35 PM	3:30 PM	Erin Dunman	86	Partly Cloudy	16.1	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
57	PETER PHILLIPS A 2	6/11/2018	11:30 AM	12:20 PM	Erin Dunman	81	Clear	2.1	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
58	PHILLIPS A 1	9/21/2017	3:00 PM	3:46 PM	Erin Dunman	89	Clear	6	FLIR G320 optical gas imaging camera		No fugitive emissions detected			

Facility Record No. * (Select from dropdown list - may need to scroll up)	Identification of Each Affected Facility * (\$60.5420a(b)(1))	Date of Survey * (\$60.5420a(b)(7)(i))	Survey Begin Time * (\$60.5420a(b)(7)(iii))	Survey End Time * (\$60.5420a(b)(7)(iii))	Name of Surveyor * (\$60.5420a(b)(7)(iii))	Ambient Temperature During Survey * (\$60.5420a(b)(7)(v))	Sky Conditions During Survey * (\$60.5420a(b)(7)(iv))	Maximum Wind Speed During Survey * (\$60.5420a(b)(7)(iv))	Monitoring Instrument Used * (\$60.5420a(b)(7)(vi))	Deviations From Monitoring Plan (If none, state none.) * (\$60.5420a(b)(7)(vii))	Type of Component for which Fugitive Emissions Detected * (\$60.5420a(b)(7)(vii))	Number of Each Component Type for which Fugitive Emissions Detected * (\$60.5420a(b)(7)(viii))	Type of Component Not Repaired as Required in § 60.5397a(h) * (\$60.5420a(b)(7)(viii))	Number of Each Component Type Not Repaired as Required in § 60.5397a(h) * (\$60.5420a(b)(7)(viii))
58	PHILLIPS A 1	6/11/2018	1:45 PM	2:19 PM	Erin Dunman	84	Clear	6.2	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
79	PHILLIPS A 3 R 2	6/11/2018	1:45 PM	2:19 PM	Erin Dunman	84	Clear	6.2	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
27	PICCOLI A 1	11/16/2017	2:44 PM	3:07 PM	Erin Dunman	60	Cloudy	2.4	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
27	PICCOLI A 1	6/11/2018	1:13 PM	1:38 PM	Erin Dunman	83	Clear	7.2	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
80	PICCOLI A 2	6/5/2018	10:24 AM	11:00 AM	Erin Dunman	76	Clear	0.7	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
81	PICCOLI A 3	6/5/2018	10:24 AM	11:00 AM	Erin Dunman	76	Clear	0.7	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
28	PICCOLI A 4	11/16/2017	1:40 PM	2:20 PM	Erin Dunman	56	Cloudy	1.5	FLIR G320 optical gas imaging camera		Connector	1		
28	PICCOLI A 4	6/5/2018	10:24 AM	11:00 AM	Erin Dunman	76	Clear	0.7	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
29	RHODES 1	11/13/2017	3:15 PM	3:47 PM	Erin Dunman	64	Clear	3.9	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
29	RHODES 2	5/29/2018	11:35 AM	12:00 PM	Erin Dunman	70	Clear	6.3	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
82	SALVADOR A 1	12/11/2017	1:48 PM	2:05 PM	Erin Dunman	48	Clear	1.9	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
82	SALVADOR A 1	3/14/2018	1:00 PM	2:30 PM	Erin Dunman	67	Partly Cloudy	4.5	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
82	SALVADOR A 1	6/26/2018	10:30 AM	11:30 PM	Erin Dunman	88	Clear	5.8	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
30	SALVADOR A 2	11/3/2017	1:31 PM	2:16 PM	Erin Dunman	57	Clear	2.2	FLIR G320 optical gas imaging camera		Connector	1		

Facility Record No. * (Select from dropdown list - may need to scroll up)	Identification of Each Affected Facility * (\$60.5420a(b)(1))	Date of Survey * (\$60.5420a(b)(7)(i))	Survey Begin Time * (\$60.5420a(b)(7)(ii))	Survey End Time * (\$60.5420a(b)(7)(iii))	Name of Surveyor * (\$60.5420a(b)(7)(iii))	Ambient Temperature During Survey * (\$60.5420a(b)(7)(v))	Sky Conditions During Survey * (\$60.5420a(b)(7)(iv))	Maximum Wind Speed During Survey * (\$60.5420a(b)(7)(iv))	Monitoring Instrument Used * (\$60.5420a(b)(7)(v))	Deviations From Monitoring Plan (If none, state none.) * (\$60.5420a(b)(7)(vi))	Type of Component for which Fugitive Emissions Detected * (\$60.5420a(b)(7)(vii))	Number of Each Component Type for which Fugitive Emissions Detected * (\$60.5420a(b)(7)(viii))	Type of Component Not Repaired as Required in § 60.5397a(h) * (\$60.5420a(b)(7)(viii))	Number of Each Component Type Not Repaired as Required in § 60.5397a(h) * (\$60.5420a(b)(7)(viii))
30	SALVADOR A 2	4/25/2018	1:30 PM	2:00 PM	Erin Dunman	71	Clear	2.8	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
31	SALVADOR A 4	11/3/2017	1:31 PM	2:16 PM	Erin Dunman	57	Clear	2.2	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
31	SALVADOR A 4	4/25/2018	1:30 PM	2:00 PM	Erin Dunman	71	Clear	2.8	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
55	SALVADOR I/II CENTRAL DELIVERY POINT	9/28/2017	1:30 PM	4:30 PM	Erin Dunman	65	Partly Cloudy	8.7	FLIR G320 optical gas imaging camera		Compressor, Connector	3 Compressor & 1 Connector		
55	SALVADOR I/II CENTRAL DELIVERY POINT	12/11/2017	1:42 PM	4:02 PM	Erin Dunman	48	Clear	1.9	FLIR G320 optical gas imaging camera		Connector, Open-Ended Line, Instrument,	6 Connector, Open-Ended Line, 2 Instrument,		
55	SALVADOR I/II CENTRAL DELIVERY POINT	3/14/2018	1:00 PM	4:30 PM	Erin Dunman	67	Partly Cloudy	4.5	FLIR G320 optical gas imaging camera		Instrument, Connector, Flange	3 Instrument, Connector, Flange		
55	SALVADOR I/II CENTRAL DELIVERY POINT	6/26/2018	2:48 PM	5:30 PM	Erin Dunman	88	Clear	5.8	FLIR G320 optical gas imaging camera		Connector, Instrument	3 Connector, Instrument		
83	SEMLER A 2	3/28/2018	11:20 AM	11:50 AM	Erin Dunman	39	Partly Cloudy	3.4	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
84	SEMLER A 4	10/12/2017	11:55 AM	12:29 AM	Erin Dunman	63	Partly Cloudy	1.4	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
84	SEMLER A 4	3/28/2018	11:20 AM	11:50 AM	Erin Dunman	39	Partly Cloudy	3.4	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
32	SNOOK B 1A FT	5/10/2018	12:30 PM	12:51 PM	Erin Dunman	83	Clear	7.7	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
32	SNOOK B 1A FT	11/14/2017	3:28 PM	4:00 PM	Erin Dunman	63	Partly Cloudy	8.8	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
33	SOUTHERN UTE 1-8 1	11/1/2017	12:10 PM	12:36 AM	Erin Dunman	57	Clear	7.2	FLIR G320 optical gas imaging camera		Valve	1		
33	SOUTHERN UTE 1-8 1	5/10/2018	11:36 AM	12:18 AM	Erin Dunman	77	Clear	2.3	FLIR G320 optical gas imaging camera		Instrument	1		

Facility Record No. * (Select from dropdown list - may need to scroll up)	Identification of Each Affected Facility * (\$60.5420a(b)(1))	Date of Survey * (\$60.5420a(b)(7)(i))	Survey Begin Time * (\$60.5420a(b)(7)(ii))	Survey End Time * (\$60.5420a(b)(7)(iii))	Name of Surveyor * (\$60.5420a(b)(7)(iv))	Ambient Temperature During Survey * (\$60.5420a(b)(7)(v))	Sky Conditions During Survey * (\$60.5420a(b)(7)(vi))	Maximum Wind Speed During Survey * (\$60.5420a(b)(7)(vii))	Monitoring Instrument Used * (\$60.5420a(b)(7)(viii))	Deviations From Monitoring Plan (If none, state none.) * (\$60.5420a(b)(7)(ix))	Type of Component for which Fugitive Emissions Detected * (\$60.5420a(b)(7)(x))	Number of Each Component Type for which Fugitive Emissions Detected * (\$60.5420a(b)(7)(xi))	Type of Component Not Repaired as Required in § 60.5397a(h) * (\$60.5420a(b)(7)(xii))	Number of Each Component Type Not Repaired as Required in § 60.5397a(h) * (\$60.5420a(b)(7)(xiii))
85	SOUTHERN UTE 32 08 02 07	5/22/2018	1:39 PM	2:10 PM	Erin Dunman	68	Cloudy	6.3	FLIR G320 optical gas imaging camera		Connector	2		
54	SOUTHERN UTE 33- 1	5/9/2018	1:10 PM	1:40 PM	Erin Dunman	70	Clear	3.3	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
54	SOUTHERN UTE 33- 1	11/1/2017	10:13 AM	10:52 AM	Erin Dunman	44	Clear	1.2	FLIR G320 optical gas imaging camera		Connector, Instrument, Flange	2 Connector, 1 Instrument, 1 Flange		
34	SOUTHERN UTE 33- 10 21- 1 2	5/31/2018	11:55 AM	12:31 PM	Erin Dunman	79	Clear	2.6	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
34	SOUTHERN UTE 33- 10 21- 1 2	11/14/2017	11:14 AM	11:45 AM	Erin Dunman	53	Partly Cloudy	2.2	FLIR G320 optical gas imaging camera		Instrument	1		
59	SOUTHERN UTE AG 1	8/25/2017	11:36 AM	12:25 PM	Erin Dunman	71	Clear	8.1	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
59	SOUTHERN UTE AG 1	5/9/2018	2:08 PM	2:30 PM	Erin Dunman	70	Clear	3.3	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
86	SOUTHERN UTE AK 2	5/22/2018	1:16 PM	2:01 PM	Erin Dunman	70	Cloudy	3.9	FLIR G320 optical gas imaging camera		Connector	2		
35	SOUTHERN UTE ALLOTTEE BC 2	10/17/2017	1:30 PM	2:15 PM	Erin Dunman	70	Partly Cloudy	1.5	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
35	SOUTHERN UTE ALLOTTEE BC 2	3/1/2018	1:50 PM	2:25 PM	Erin Dunman	45	Clear	3.6	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
36	SOUTHERN UTE AX 2	11/3/2017	10:59 AM	11:36 AM	Erin Dunman	50	Clear	1.8	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
36	SOUTHERN UTE AX 2	5/7/2018	11:40 AM	12:30 PM	Erin Dunman	79	Partly Cloudy	6.9	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
37	SOUTHERN UTE AX 4	11/3/2017	10:59 AM	11:36 AM	Erin Dunman	50	Clear	1.8	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
37	SOUTHERN UTE AX 4	5/7/2018	11:40 AM	12:30 PM	Erin Dunman	79	Partly Cloudy	6.9	FLIR G320 optical gas imaging camera		No fugitive emissions detected			

Facility Record No. * (Select from dropdown list - may need to scroll up)	Identification of Each Affected Facility * (\$60.5420a(b)(1))	Date of Survey * (\$60.5420a(b)(7)(i))	Survey Begin Time * (\$60.5420a(b)(7)(ii))	Survey End Time * (\$60.5420a(b)(7)(iii))	Name of Surveyor * (\$60.5420a(b)(7)(iv))	Ambient Temperature During Survey * (\$60.5420a(b)(7)(v))	Sky Conditions During Survey * (\$60.5420a(b)(7)(vi))	Maximum Wind Speed During Survey * (\$60.5420a(b)(7)(vii))	Monitoring Instrument Used * (\$60.5420a(b)(7)(viii))	Deviations From Monitoring Plan (if none, state none.) * (\$60.5420a(b)(7)(ix))	Type of Component for which Fugitive Emissions Detected * (\$60.5420a(b)(7)(x))	Number of Each Component Type for which Fugitive Emissions Detected * (\$60.5420a(b)(7)(xi))	Type of Component Not Repaired as Required in § 60.5397a(h) * (\$60.5420a(b)(7)(xii))	Number of Each Component Type Not Repaired as Required in § 60.5397a(h) * (\$60.5420a(b)(7)(xiii))
87	SOUTHERN UTE M 1	5/24/2018	10:40 AM	11:15 AM	Erin Dunman	70	Clear	5.8	FLIR G320 optical gas imaging camera		Instrument	1		
60	SOUTHERN UTE M 2	9/21/2017	1:50 PM	2:22 PM	Erin Dunman	78	Clear	2.5	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
60	SOUTHERN UTE M 2	5/10/2018	2:16 PM	2:40 PM	Erin Dunman	82	Clear	9.5	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
38	SOUTHERN UTE TRIBAL A 5-1	5/1/2018	11:48 PM	12:14 PM	Erin Dunman	59	Cloudy	5.8	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
38	SOUTHERN UTE TRIBAL A 5-1	10/26/2017	11:50 AM	12:25 PM	Erin Dunman	54	Partly Cloudy	2.5	FLIR G320 optical gas imaging camera		Connector, Valve	1 Connector & 1 Valve		
88	SOUTHERN UTE TRIBAL BK 1	4/25/2018	1:20 PM	2:00 PM	Erin Dunman	68	Clear	2.8	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
48	SOUTHERN UTE TRIBAL BK 2	11/6/2017	1:40 PM	2:11 PM	Erin Dunman	58	Cloudy	4.6	FLIR G320 optical gas imaging camera		Instrument	1		
48	SOUTHERN UTE TRIBAL BK 2	6/19/2018	11:15 AM	11:50 AM	Erin Dunman	79	Clear	6.1	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
39	SOUTHERN UTE TRIBAL BK 4	11/8/2017	11:48 AM	12:32 AM	Erin Dunman	42	Clear	2.2	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
39	SOUTHERN UTE TRIBAL BK 4	4/25/2018	1:20 PM	1:50 PM	Erin Dunman	68	Clear	2.8	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
40	SOUTHERN UTE TRIBAL D 2	11/6/2017	2:28 PM	2:56 PM	Erin Dunman	57	Cloudy	3.5	FLIR G320 optical gas imaging camera		Connector	1		
40	SOUTHERN UTE TRIBAL D 2	5/18/2018	10:16 AM	10:43 AM	Erin Dunman	66	Clear	3	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
89	SOUTHERN UTE TRIBAL E 1	4/25/2018	12:53 PM	1:53 AM	Erin Dunman	71	Clear	2.8	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
90	SOUTHERN UTE TRIBAL E 2	3/27/2018	1:40 PM	2:22 PM	Erin Dunman	38	Cloudy	1.7	FLIR G320 optical gas imaging camera		No fugitive emissions detected			

Facility Record No. * (Select from dropdown list - may need to scroll up)	Identification of Each Affected Facility * (§60.5420a(b)(1))	Date of Survey * (§60.5420a(b)(7)(i))	Survey Begin Time * (§60.5420a(b)(7)(ii))	Survey End Time * (§60.5420a(b)(7)(iii))	Name of Surveyor * (§60.5420a(b)(7)(iii))	Ambient Temperature During Survey * (§60.5420a(b)(7)(iv))	Sky Conditions During Survey * (§60.5420a(b)(7)(iv))	Maximum Wind Speed During Survey * (§60.5420a(b)(7)(iv))	Monitoring Instrument Used * (§60.5420a(b)(7)(v))	Deviations From Monitoring Plan (If none, state none.) * (§60.5420a(b)(7)(vi))	Type of Component for which Fugitive Emissions Detected * (§60.5420a(b)(7)(vii))	Number of Each Component Type for which Fugitive Emissions Detected * (§60.5420a(b)(7)(viii))	Type of Component Not Repaired as Required in §60.5397a(h) * (§60.5420a(b)(7)(viii))	Number of Each Component Type Not Repaired as Required in §60.5397a(h) * (§60.5420a(b)(7)(viii))
51	SOUTHERN UTE TRIBAL E 3	11/8/2017	12:53 PM	1:21 PM	Erin Dunman	43	Clear	3.1	FLIR G320 optical gas imaging camera		Instrument	1		
51	SOUTHERN UTE TRIBAL E 3	4/25/2018	12:54 PM	1:54 AM	Erin Dunman	71	Clear	2.8	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
91	SOUTHERN UTE TRIBAL K 1	4/24/2018	1:35 PM	2:01 PM	Erin Dunman	68	Clear	2.4	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
49	SOUTHERN UTE TRIBAL K 4	11/6/2017	12:47 PM	1:17 PM	Erin Dunman	55	Cloudy	2.8	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
49	SOUTHERN UTE TRIBAL K 4	4/24/2018	1:30 PM	2:01 PM	Erin Dunman	68	Clear	2.4	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
41	SOUTHERN UTE TRIBAL L 3	11/8/2017	2:40 PM	3:40 PM	Erin Dunman	50	Clear	2.4	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
41	SOUTHERN UTE TRIBAL L 3	4/25/2018	2:47 PM	3:15 PM	Erin Dunman	74	Clear	4.1	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
42	SOUTHERN UTE TRIBAL L 4	11/8/2017	11:48 AM	12:32 PM	Erin Dunman	42	Clear	2.2	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
42	SOUTHERN UTE TRIBAL L 4	4/25/2018	1:20 PM	2:00 PM	Erin Dunman	68	Clear	2.8	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
43	SOUTHERN UTE TRIBAL O 1	11/1/2017	11:06 AM	11:49 AM	Erin Dunman	48	Clear	1.6	FLIR G320 optical gas imaging camera		Connector, Flange	1 Connector, 1 Flange		
43	SOUTHERN UTE TRIBAL O 1	5/10/2018	10:45 AM	11:26 AM	Erin Dunman	72	Clear	2.7	FLIR G320 optical gas imaging camera		Connector	1		
50	SOUTHERN UTE TRIBAL O 3	11/1/2017	11:06 AM	11:49 AM	Erin Dunman	48	Clear	1.5	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
50	SOUTHERN UTE TRIBAL O 3	5/10/2018	10:45 AM	11:26 AM	Erin Dunman	72	Clear	2.7	FLIR G320 optical gas imaging camera		Valve	1		
44	SOUTHERN UTE TRIBAL V 1	11/1/2017	12:40 PM	1:10 PM	Erin Dunman	59	Clear	7	FLIR G320 optical gas imaging camera		No fugitive emissions detected			

Facility Record No. * (Select from dropdown list - may need to scroll up)	Identification of Each Affected Facility * (\$60.5420a(b)(1))	Date of Survey * (\$60.5420a(b)(7)(i))	Survey Begin Time * (\$60.5420a(b)(7)(ii))	Survey End Time * (\$60.5420a(b)(7)(iii))	Name of Surveyor * (\$60.5420a(b)(7)(iii))	Ambient Temperature During Survey * (\$60.5420a(b)(7)(vi))	Sky Conditions During Survey * (\$60.5420a(b)(7)(iv))	Maximum Wind Speed During Survey * (\$60.5420a(b)(7)(iv))	Monitoring Instrument Used * (\$60.5420a(b)(7)(v))	Deviations From Monitoring Plan (if none, state none.) * (\$60.5420a(b)(7)(vi))	Type of Component for which Fugitive Emissions Detected * (\$60.5420a(b)(7)(viii))	Number of Each Component Type for which Fugitive Emissions Detected * (\$60.5420a(b)(7)(viii))	Type of Component Not Repaired as Required in § 60.5397a(h) * (\$60.5420a(b)(7)(viii))	Number of Each Component Type Not Repaired as Required in § 60.5397a(h) * (\$60.5420a(b)(7)(viii))
44	SOUTHERN LITE TRIBAL V 1	4/25/2018	3:45 PM	4:33 PM	Erin Dunman	76	Clear	3.8	FLIR G320 optical gas imaging camera		Connector	1		
92	STATE MZ 1 R	5/29/2018	11:35 AM	12:00 PM	Erin Dunman	70	Clear	6.3	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
93	STATE MZ 2	11/30/2018	11:52 AM	12:24 AM	Erin Dunman	44	Cloudy	1.6	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
93	STATE MZ 2	5/29/2018	11:13 AM	11:31 AM	Erin Dunman	70	Clear	6.3	FLIR G320 optical gas imaging camera		Connector	1		
94	TIFFANY 1 1	10/3/2017	12:36 PM	1:25 PM	Erin Dunman	83	Clear	3.2	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
94	TIFFANY 1 1	4/10/2018	12:20 PM	1:26 PM	Erin Dunman	67	Clear	5.1	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
95	TIFFANY 1 2	10/3/2017	12:50 PM	1:31 PM	Erin Dunman	83	Clear	3.2	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
95	TIFFANY 1 2	4/10/2018	12:20 PM	1:26 PM	Erin Dunman	67	Clear	5.1	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
96	TIFFANY 1 3	10/3/2017	12:50 PM	1:34 PM	Erin Dunman	83	Clear	3.2	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
96	TIFFANY 1 3	4/10/2018	12:20 PM	1:26 PM	Erin Dunman	67	Clear	5.1	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
97	TIFFANY 1 4	10/3/2017	1:00 PM	1:35 PM	Erin Dunman	83	Clear	3.2	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
97	TIFFANY 1 4	4/10/2018	12:20 PM	1:26 PM	Erin Dunman	67	Clear	5.1	FLIR G320 optical gas imaging camera		Connector	1		
98	TIFFANY 2 2	1/30/2018	12:27 PM	12:44 PM	Erin Dunman	52	Clear	1.3	FLIR G320 optical gas imaging camera		Instrument, Flange	1 Instrument, 1 Flange		
99	TIFFANY 2 3	1/30/2018	12:27 PM	12:44 PM	Erin Dunman	52	Clear	1.3	FLIR G320 optical gas imaging camera		Valve	1		

Facility Record No. * (Select from dropdown list - may need to scroll up)	Identification of Each Affected Facility * (\$60.5420a(b)(1))	Date of Survey * (\$60.5420a(b)(7)(i))	Survey Begin Time * (\$60.5420a(b)(7)(ii))	Survey End Time * (\$60.5420a(b)(7)(iii))	Name of Surveyor * (\$60.5420a(b)(7)(iii))	Ambient Temperature During Survey * (\$60.5420a(b)(7)(iv))	Sky Conditions During Survey * (\$60.5420a(b)(7)(iv))	Maximum Wind Speed During Survey * (\$60.5420a(b)(7)(iv))	Monitoring Instrument Used * (\$60.5420a(b)(7)(vi))	Deviations From Monitoring Plan (If none, state none.) * (\$60.5420a(b)(7)(vi))	Type of Component for which Fugitive Emissions Detected * (\$60.5420a(b)(7)(viii))	Number of Each Component Type for which Fugitive Emissions Detected * (\$60.5420a(b)(7)(viii))	Type of Component Not Repaired as Required in § 60.5397a(h) * (\$60.5420a(b)(7)(viii))	Number of Each Component Type Not Repaired as Required in § 60.5397a(h) * (\$60.5420a(b)(7)(viii))
100	TIFFANY 4 1	4/16/2018	11:30 AM	12:30 PM	Erin Dunman	62	Cloudy	6	FLIR G320 optical gas imaging camera		Connector, Instrument, Open-Ended Line	1 Connector, 1 Instrument, 1 Open-Ended Line		
101	TIFFANY 4 2	4/16/2018	11:30 AM	12:30 PM	Erin Dunman	62	Cloudy	6	FLIR G320 optical gas imaging camera		Connector	1		
102	TIFFANY 4 3	4/16/2018	11:30 AM	12:30 PM	Erin Dunman	62	Cloudy	6	FLIR G320 optical gas imaging camera		Valve	1		
45	UTE AA 1	11/6/2017	3:03 PM	3:32 PM	Erin Dunman	59	Cloudy	2.7	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
45	UTE AA 1	5/18/2018	10:45 AM	11:02 AM	Erin Dunman	67	Clear	4.2	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
10	WARREN DAVIS C 2	11/14/2017	3:28 PM	3:56 PM	Erin Dunman	63	Partly Cloudy	3.8	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
10	WARREN DAVIS C 2	6/5/2018	1:30 PM	2:40 PM	Erin Dunman	89	Clear	3.9	FLIR G320 optical gas imaging camera		Connector	1		
103	WEBB REEDER A 2	4/26/2018	2:15 PM	2:38 PM	Erin Dunman	77	Clear	4.4	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
46	WEBB REEDER B 2	11/15/2017	3:30 PM	4:05 PM	Erin Dunman	59	Partly Cloudy	0.8	FLIR G320 optical gas imaging camera		Valve, Open-Ended Line	1 Valve, 1 Open-Ended Line		
47	WRIGHT 01 19 1	11/13/2017	3:28 PM	3:54 PM	Erin Dunman	63	Clear	2.2	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
47	WRIGHT 01 19 1	5/29/2018	10:40 AM	11:03 AM	Erin Dunman	68	Clear	2.7	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
104	YANKEE FEDERAL A 2	12/13/2017	12:01 PM	12:28 PM	Erin Dunman	43	Partly Cloudy	1.3	FLIR G320 optical gas imaging camera		No fugitive emissions detected			
104	YANKEE FEDERAL A 2	5/29/2018	1:04 PM	1:48 PM	Erin Dunman	70	Clear	3.3	FLIR G320 optical gas imaging camera		No fugitive emissions detected			

Reconstruction Commenced After September 18, 2015 - 60.5420a(b) Annual Report										
in paragraphs (b)(7)(i) through (xii) of this section in all annual reports:										
										OGI
Facility Record No. * (Select from dropdown list - may need to scroll up)	Type of Difficult-to-Monitor Components Monitored * (\$60.5420a(b)(7)(i)(x))	Number of Each Difficult-to-Monitor Component Type Monitored * (\$60.5420a(b)(7)(i)(x))	Type of Unsafe-to-Monitor Component Monitored * (\$60.5420a(b)(7)(i)(x))	Number of Each Unsafe-to-Monitor Component Type Monitored * (\$60.5420a(b)(7)(i)(x))	Date of Successful Repair of Fugitive Emissions Component * (\$60.5420a(b)(7)(x))	Type of Component Placed on Delay of Repair * (\$60.5420a(b)(7)(x))	Number of Each Component Type Placed on Delay of Repair * (\$60.5420a(b)(7)(x))	Explanation for Delay of Repair * (\$60.5420a(b)(7)(x))	Type of Instrument Used to Resurvey Repaired Components Not Repaired During Original Survey * (\$60.5420a(b)(7)(x))	Training and Experience of Surveyor * (\$60.5420a(b)(7)(iii))
	e.g.: Valve	e.g.: 1	e.g.: Valve	e.g.: 1	e.g.: 11/10/16	e.g.: Valve	e.g.: 1	e.g.: Unsafe to repair until next shutdown	e.g.: Company ABC optical gas imaging camera	e.g.: Trained thermographer; completed 40-hour course at XYZ Training Center. Has 10 years of experience with OGI surveys.
1					11/18/2017				Method 21 - Soap bubbles	Trained thermographer; completed Infrared Training Center Optical Gas imaging course which included classroom and field training. Has 8 years of experience with BP.
1										Trained thermographer; completed Infrared Training Center Optical Gas imaging course which included classroom and field training. Has 8 years of experience with BP.
2					11/18/2017				Method 21 - Soap bubbles	Trained thermographer; completed Infrared Training Center Optical Gas imaging course which included classroom and field training. Has 8 years of experience with BP.
2										Trained thermographer; completed Infrared Training Center Optical Gas imaging course which included classroom and field training. Has 8 years of experience with BP.
3										Trained thermographer; completed Infrared Training Center Optical Gas imaging course which included classroom and field training. Has 8 years of experience with BP.
3					5/2/2018				Method 21 - Soap bubbles	Trained thermographer; completed Infrared Training Center Optical Gas imaging course which included classroom and field training. Has 8 years of experience with BP.
62					5/2/2018				Method 21 - Soap bubbles	Trained thermographer; completed Infrared Training Center Optical Gas imaging course which included classroom and field training. Has 8 years of experience with BP.
19										Trained thermographer; completed Infrared Training Center Optical Gas imaging course which included classroom and field training. Has 8 years of experience with BP.
19										Trained thermographer; completed Infrared Training Center Optical Gas imaging course which included classroom and field training. Has 8 years of experience with BP.
7					12/12/2017				Method 21 - Soap bubbles	Trained thermographer; completed Infrared Training Center Optical Gas imaging course which included classroom and field training. Has 8 years of experience with BP.
7					6/7/2018				Method 21 - Soap bubbles	Trained thermographer; completed Infrared Training Center Optical Gas imaging course which included classroom and field training. Has 8 years of experience with BP.
4										Trained thermographer; completed Infrared Training Center Optical Gas imaging course which included classroom and field training. Has 8 years of experience with BP.

Facility Record No. * (Select from dropdown list - may need to scroll up)	Type of Difficult- to-Monitor Components Monitored * (\$60.5420a(b)(7)(i) x))	Number of Each Difficult-to- Monitor Component Type Monitored * (\$60.5420a(b)(7)(i) x))	Type of Unsafe-to- Monitor Component Monitored * (\$60.5420a(b)(7)(i) x))	Number of Each Unsafe-to- Monitor Component Type Monitored * (\$60.5420a(b)(7)(i) x))	Date of Successful Repair of Fugitive Emissions Component * (\$60.5420a(b)(7)(x))	Type of Component Placed on Delay of Repair * (\$60.5420a(b)(7)(x))	Number of Each Component Type Placed on Delay of Repair * (\$60.5420a(b)(7)(x))	Explanation for Delay of Repair * (\$60.5420a(b)(7)(x))	Type of Instrument Used to Resurvey Repaired Components Not Repaired During Original Survey * (\$60.5420a(b)(7)(x))	Training and Experience of Surveyor * (\$60.5420a(b)(7)(iii))
4										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
61					10/12/2017				Method 21 - Soap bubbles	Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
61										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
63										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
5										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
5										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
64										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
64										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
6					10/13/2017				Method 21 - Soap bubbles	Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
6					4/5/2018				Method 21 - Soap bubbles	Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
65										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
17					11/22/2017				Method 21 - Soap bubbles	Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
17										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
52					11/8/2017				Method 21 - Soap bubbles	Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.

Facility Record No. * (Select from dropdown list - may need to scroll up)	Type of Difficult-to-Monitor Components Monitored * (\$60.5420a(b)(7)(i)(x))	Number of Each Difficult-to-Monitor Component Type Monitored * (\$60.5420a(b)(7)(i)(x))	Type of Unsafe-to-Monitor Component Monitored * (\$60.5420a(b)(7)(i)(x))	Number of Each Unsafe-to-Monitor Component Type Monitored * (\$60.5420a(b)(7)(i)(x))	Date of Successful Repair of Fugitive Emissions Component * (\$60.5420a(b)(7)(x))	Type of Component Placed on Delay of Repair * (\$60.5420a(b)(7)(x))	Number of Each Component Type Placed on Delay of Repair * (\$60.5420a(b)(7)(x))	Explanation for Delay of Repair * (\$60.5420a(b)(7)(x))	Type of Instrument Used to Resurvey Repaired Components Not Repaired During Original Survey * (\$60.5420a(b)(7)(xiii))	Training and Experience of Surveyor * (\$60.5420a(b)(7)(iii))
52					6/13/2018				Method 21 - Soap bubbles	Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
8										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
8										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
9					12/12/2017				Method 21 - Soap bubbles	Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
9										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
66										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
66										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
67										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
67										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
12										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
11										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
11										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
12					12/13/2017				Method 21 - Soap bubbles	Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
13					6/21/2018				Method 21 - Soap bubbles	Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.

Facility Record No. * (Select from dropdown list - may need to scroll up)	Type of Difficult-to-Monitor Components Monitored * (\$60.5420a(b)(7)(i)(x))	Number of Each Difficult-to-Monitor Component Type Monitored * (\$60.5420a(b)(7)(i)(x))	Type of Unsafe-to-Monitor Component Monitored * (\$60.5420a(b)(7)(i)(x))	Number of Each Unsafe-to-Monitor Component Type Monitored * (\$60.5420a(b)(7)(i)(x))	Date of Successful Repair of Fugitive Emissions Component * (\$60.5420a(b)(7)(x))	Type of Component Placed on Delay of Repair * (\$60.5420a(b)(7)(xi))	Number of Each Component Type Placed on Delay of Repair * (\$60.5420a(b)(7)(xi))	Explanation for Delay of Repair * (\$60.5420a(b)(7)(xi))	Type of Instrument Used to Resurvey Repaired Components Not Repaired During Original Survey * (\$60.5420a(b)(7)(xii))	Training and Experience of Surveyor * (\$60.5420a(b)(7)(iii))
13					12/12/2017				Method 21 - Soap bubbles	Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
69										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
68										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
68										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
14					10/25/2017				Method 21 - Soap bubbles	Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
14										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
15					10/25/2017				Method 21 - Soap bubbles	Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
15										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
16										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
16										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
70					6/14/2018				Method 21 - Soap bubbles	Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
71										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
18										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
18					5/21/2018				Method 21 - Soap bubbles	Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.

Facility Record No. * (Select from dropdown list - may need to scroll up)	Type of Difficult- to-Monitor Components Monitored * (\$60.5420a(b)(7)(i) x))	Number of Each Difficult-to- Monitor Component Type Monitored * (\$60.5420a(b)(7)(i) x))	Type of Unsafe-to- Monitor Component Monitored * (\$60.5420a(b)(7)(i) x))	Number of Each Unsafe-to- Monitor Component Type Monitored * (\$60.5420a(b)(7)(i) x))	Date of Successful Repair of Fugitive Emissions Component * (\$60.5420a(b)(7)(x))	Type of Component Placed on Delay of Repair * (\$60.5420a(b)(7)(i) x))	Number of Each Component Type Placed on Delay of Repair * (\$60.5420a(b)(7)(i) x))	Explanation for Delay of Repair * (\$60.5420a(b)(7)(i) x))	Type of Instrument Used to Resurvey Repaired Components Not Repaired During Original Survey * (\$60.5420a(b)(7)(xii))	Training and Experience of Surveyor * (\$60.5420a(b)(7)(iii))
72										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
73										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
56										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
56										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
74										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
20					11/22/2017				Method 21 - Soap bubbles	Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
20										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
21					11/29/2017				Method 21 - Soap bubbles	Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
21										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
75					5/4/2018				Method 21 - Soap bubbles	Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
76										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
53										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
53					6/5/2018				Method 21 - Soap bubbles	Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
77										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.

Facility Record No. * [Select from dropdown list - may need to scroll up]	Type of Difficult- to-Monitor Components Monitored * (\$60.5420a(b)(7)(i) x))	Number of Each Difficult-to- Monitor Component Type Monitored * (\$60.5420a(b)(7)(i) x))	Type of Unsafe-to- Monitor Component Monitored * (\$60.5420a(b)(7)(i) x))	Number of Each Unsafe-to- Monitor Component Type Monitored * (\$60.5420a(b)(7)(i) x))	Date of Successful Repair of Fugitive Emissions Component * (\$60.5420a(b)(7)(x))	Type of Component Placed on Delay of Repair * (\$60.5420a(b)(7)(xi))	Number of Each Component Type Placed on Delay of Repair * (\$60.5420a(b)(7)(xi))	Explanation for Delay of Repair * (\$60.5420a(b)(7)(xi))	Type of Instrument Used to Resurvey Repaired Components Not Repaired During Original Survey * (\$60.5420a(b)(7)(xii))	Training and Experience of Surveyor * (\$60.5420a(b)(7)(iii))
78										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
22					10/25/2017				Method 21 - Soap bubbles	Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
22										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
23										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
23										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
24										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
24										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
25										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
25										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
26					12/13/2017				Method 21 - Soap bubbles	Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
26										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
57										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
57										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
58										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.

Facility Record No. * (Select from dropdown list - may need to scroll up)	Type of Difficult-to-Monitor Components Monitored * (\$60.5420a(b)(7)(i)(x))	Number of Each Difficult-to-Monitor Component Type Monitored * (\$60.5420a(b)(7)(i)(x))	Type of Unsafe-to-Monitor Component Monitored * (\$60.5420a(b)(7)(i)(x))	Number of Each Unsafe-to-Monitor Component Type Monitored * (\$60.5420a(b)(7)(i)(x))	Date of Successful Repair of Fugitive Emissions Component * (\$60.5420a(b)(7)(k))	Type of Component Placed on Delay of Repair * (\$60.5420a(b)(7)(xi))	Number of Each Component Type Placed on Delay of Repair * (\$60.5420a(b)(7)(xi))	Explanation for Delay of Repair * (\$60.5420a(b)(7)(xii))	Type of Instrument Used to Resurvey Repaired Components Not Repaired During Original Survey * (\$60.5420a(b)(7)(xiii))	Training and Experience of Surveyor * (\$60.5420a(b)(7)(iii))
58										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
79										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
27										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
27										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
80										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
81										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
28					12/6/2017				Method 21 - Soap bubbles	Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
28										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
29										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
29										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
82										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
82										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
82										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
30					11/22/2017				Method 21 - Soap bubbles	Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.

Facility Record No. * (Select from dropdown list - may need to scroll up)	Type of Difficult-to-Monitor Components Monitored * (\$60.5420a(b)(7)(i)(x))	Number of Each Difficult-to-Monitor Component Type Monitored * (\$60.5420a(b)(7)(i)(x))	Type of Unsafe-to-Monitor Component Monitored * (\$60.5420a(b)(7)(i)(x))	Number of Each Unsafe-to-Monitor Component Type Monitored * (\$60.5420a(b)(7)(i)(x))	Date of Successful Repair of Fugitive Emissions Component * (\$60.5420a(b)(7)(x))	Type of Component Placed on Delay of Repair * (\$60.5420a(b)(7)(xi))	Number of Each Component Type Placed on Delay of Repair * (\$60.5420a(b)(7)(xi))	Explanation for Delay of Repair * (\$60.5420a(b)(7)(xi))	Type of Instrument Used to Resurvey Repaired Components Not Repaired During Original Survey * (\$60.5420a(b)(7)(xii))	Training and Experience of Surveyor * (\$60.5420a(b)(7)(iii))
30										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
31										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
31										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
55					10/23/2017				Method 21 - Soap bubbles	Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
55					1/3/2018				Method 21 - Soap bubbles	Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
55					3/21/2018				Method 21 - Soap bubbles	Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
55									Method 21 - Soap bubbles	Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
83										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
84										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
84										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
32										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
32										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
33					11/22/2017				Method 21 - Soap bubbles	Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
33					5/14/2018				Method 21 - Soap bubbles	Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.

Facility Record No. * (Select from dropdown list - may need to scroll up)	Type of Difficult-to-Monitor Components Monitored * (\$60.5420a(b)(7)(i)(x))	Number of Each Difficult-to-Monitor Component Type Monitored * (\$60.5420a(b)(7)(i)(x))	Type of Unsafe-to-Monitor Component Monitored * (\$60.5420a(b)(7)(i)(x))	Number of Each Unsafe-to-Monitor Component Type Monitored * (\$60.5420a(b)(7)(i)(x))	Date of Successful Repair of Fugitive Emissions Component * (\$60.5420a(b)(7)(x))	Type of Component Placed on Delay of Repair * (\$60.5420a(b)(7)(xi))	Number of Each Component Type Placed on Delay of Repair * (\$60.5420a(b)(7)(xi))	Explanation for Delay of Repair * (\$60.5420a(b)(7)(xi))	Type of Instrument Used to Resurvey Repaired Components Not Repaired During Original Survey * (\$60.5420a(b)(7)(xii))	Training and Experience of Surveyor * (\$60.5420a(b)(7)(iii))
85					6/19/2018				Method 21 - Soap bubbles	Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
54										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
54					11/22/2018				Method 21 - Soap bubbles	Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
34										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
34					12/12/2017				Method 21 - Soap bubbles	Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
59										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
59										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
86					6/8/2018				Method 21 - Soap bubbles	Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
35										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
35										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
36										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
36										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
37										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
37										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.

Facility Record No. * (Select from dropdown list - may need to scroll up)	Type of Difficult- to-Monitor Components Monitored * (\$60.5420a(b)(7)(i) x))	Number of Each Difficult-to- Monitor Component Type Monitored * (\$60.5420a(b)(7)(i) x))	Type of Unsafe-to- Monitor Component Monitored * (\$60.5420a(b)(7)(i) x))	Number of Each Unsafe-to- Monitor Component Type Monitored * (\$60.5420a(b)(7)(i) x))	Date of Successful Repair of Fugitive Emissions Component * (\$60.5420a(b)(7)(x))	Type of Component Placed on Delay of Repair * (\$60.5420a(b)(7)(xi))	Number of Each Component Type Placed on Delay of Repair * (\$60.5420a(b)(7)(xi))	Explanation for Delay of Repair * (\$60.5420a(b)(7)(xi))	Type of Instrument Used to Resurvey Repaired Components Not Repaired During Original Survey * (\$60.5420a(b)(7)(xii))	Training and Experience of Surveyor * (\$60.5420a(b)(7)(iii))
87					6/19/2018				Method 21 - Soap bubbles	Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
60										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
60										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
38										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
38					11/2/2017				Method 21 - Soap bubbles	Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
88										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
48					11/22/2017				Method 21 - Soap bubbles	Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
48										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
39										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
39										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
40					11/22/2017				Method 21 - Soap bubbles	Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
40										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
89										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
90										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.

Facility Record No. * (Select from dropdown list - may need to scroll up)	Type of Difficult-to-Monitor Components Monitored * (\$60.5420a(b)(7)(i)(x))	Number of Each Difficult-to-Monitor Component Type Monitored * (\$60.5420a(b)(7)(i)(x))	Type of Unsafe-to-Monitor Component Monitored * (\$60.5420a(b)(7)(i)(x))	Number of Each Unsafe-to-Monitor Component Type Monitored * (\$60.5420a(b)(7)(i)(x))	Date of Successful Repair of Fugitive Emissions Component * (\$60.5420a(b)(7)(xi))	Type of Component Placed on Delay of Repair * (\$60.5420a(b)(7)(xi))	Number of Each Component Type Placed on Delay of Repair * (\$60.5420a(b)(7)(xi))	Explanation for Delay of Repair * (\$60.5420a(b)(7)(xi))	Type of Instrument Used to Resurvey Repaired Components Not Repaired During Original Survey * (\$60.5420a(b)(7)(xii))	Training and Experience of Surveyor * (\$60.5420a(b)(7)(iii))
51					11/22/2017				Method 21 - Soap bubbles	Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
51										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
91										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
49										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
49										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
41										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
41										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
42										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
42										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
43					11/22/2017				Method 21 - Soap bubbles	Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
43					5/14/2018				Method 21 - Soap bubbles	Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
50										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
50					5/14/2018				Method 21 - Soap bubbles	Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
44										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.

Facility Record No. * (Select from dropdown list - may need to scroll up)	Type of Difficult- to-Monitor Components Monitored * (\$60.5420a(b)(7)(i) x))	Number of Each Difficult-to- Monitor Component Type Monitored * (\$60.5420a(b)(7)(i) x))	Type of Unsafe-to- Monitor Component Monitored * (\$60.5420a(b)(7)(i) x))	Number of Each Unsafe-to- Monitor Component Type Monitored * (\$60.5420a(b)(7)(i) x))	Date of Successful Repair of Fugitive Emissions Component * (\$60.5420a(b)(7)(x))	Type of Component Placed on Delay of Repair * (\$60.5420a(b)(7)(x))	Number of Each Component Type Placed on Delay of Repair * (\$60.5420a(b)(7)(x))	Explanation for Delay of Repair * (\$60.5420a(b)(7)(x))	Type of Instrument Used to Resurvey Repaired Components Not Repaired During Original Survey * (\$60.5420a(b)(7)(xii))	Training and Experience of Surveyor * (\$60.5420a(b)(7)(iii))
44					5/2/2018				Method 21 - Soap bubbles	Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
92										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
93										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
93					6/15/2018				Method 21 - Soap bubbles	Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
94										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
94										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
95										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
95										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
96										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
96										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
97										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
97					4/17/2018				Method 21 - Soap bubbles	Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
98					2/13/2018				Method 21 - Soap bubbles	Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
99					2/5/2018				Method 21 - Soap bubbles	Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.

Facility Record No. * [Select from dropdown list - may need to scroll up]	Type of Difficult- to-Monitor Components Monitored * (\$60.5420a(b)(7)(i) x))	Number of Each Difficult-to- Monitor Component Type Monitored * (\$60.5420a(b)(7)(i) x))	Type of Unsafe-to- Monitor Component Monitored * (\$60.5420a(b)(7)(i) x))	Number of Each Unsafe-to- Monitor Component Type Monitored * (\$60.5420a(b)(7)(i) x))	Date of Successful Repair of Fugitive Emissions Component * (\$60.5420a(b)(7)(x))	Type of Component Placed on Delay of Repair * (\$60.5420a(b)(7)(x))	Number of Each Component Type Placed on Delay of Repair * (\$60.5420a(b)(7)(x))	Explanation for Delay of Repair * (\$60.5420a(b)(7)(x))	Type of Instrument Used to Resurvey Repaired Components Not Repaired During Original Survey * (\$60.5420a(b)(7)(x)(i))	Training and Experience of Surveyor * (\$60.5420a(b)(7)(iii))
100					4/17/2018				Method 21 - Soap bubbles	Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
101					4/17/2018				Method 21 - Soap bubbles	Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
102					4/17/2018				Method 21 - Soap bubbles	Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
45										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
45										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
10										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
10					6/7/2018				Method 21 - Soap bubbles	Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
103										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
46					11/28/2017				Method 21 - Soap bubbles	Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
47										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
47										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
104										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.
104										Trained thermographer; completed Infrared Training Center Optical Gas Imaging course which included classroom and field training. Has 8 years of experience with BP.